

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

GU977
West
> 1
1.291 mi.
6816 ft.

MANHOLE 71178
NEPTUNE AV/W37TH ST
BROOKLYN, NY

NY Spills **S103829484**
N/A

Site 2 of 5 in cluster GU

Relative:
Higher

Actual:
0 ft.

SPILLS:

Name: MANHOLE 71178
Address: NEPTUNE AV/W37TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9815386 / 2002-06-07
Facility ID: 9815386
Facility Type: ER
DER Facility ID: 131366
Site ID: 154986
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 1999-03-27
Investigator: CAENGELH
Referred To: Not reported
Reported to Dept: 1999-03-27
CID: 382
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1999-03-27
Spill Record Last Update: 2002-06-07
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: MIKE CESARE
DEC Memo:

"Prior to Sept, 2004 data translation this spill Lead_DEC Field was
ENGELHARDT Con Ed e2mis #123899: 09:41 J.MCINTYRE #4733 F.O.D CALLED
REPORTING HE FOUND 1/2 GAL UNKNOWN OIL ON TOP OF 100 GAL WATER IN
MH71178 S/S NEPTUNE AVE. 49' E/O W.37 ST. NO SEWERS OR WATERWAYS
AFFECTED. UNABLE TO ENTER MH TO CHECK FOR SUMP OR REGULATOR. A SAMPLE
WAS TAKEN PUT IN FOR 4-6 HRS. PRIORITY. CLEAN UP PENDING OIL SAMPLE
RESULTS INSTALLED E.S.TAG #13522 NO PARKING 9AM TO 10:30 AM TUESDAY &
FRIDAY. 3/27/99 18:05 -- LAB SEQ #99-03150, <1.0 PPM PCB UPDATE***
3-28-99 02:00HRS CLEANUP COMPLETED WITH SLIX & TAG # 13522 WAS SUCKED
UP INTO VACTOR. WALKER REPORTS, MH IS MAKING WATER QUICKLY FROM SUMP.
CALLED ERT AND ASKED FOR THEIR ASSISTANCE BECAUSE U.G SPLICING IS
SCHDULED FOR 8:00AM. ERT BILL WALLACE RECOMMENDS THAT WE CLOSE OUT
JOB AND WORK IT ACCORDINGLY. ALSO UNDER 50 TANKER IS ORDERED FOR MEET
WTH FLUSH AT 8:00."

Remarks: "1/2 GAL SPILL CONTAINED IN MANHOLE. CON ED 123-899. CLEAN UP PENDING
LAB RESULTS."

All Materials:

Site ID: 154986
Operable Unit ID: 1076414

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Operable Unit: 01
Material ID: 308494
Material Code: 0066A
Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported